

Print Server Compatible Tested List

Release Date: 2008/03/28

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
1.	HP	CLJ 1500L	OK		
2.	HP	CLJ 1600	OK		
3.	HP	CLJ3000dn	OK	OK	
4.	HP	CLJ 3500	OK		
5.	HP	CLJ 3500N	OK		
6.	HP	CLJ 3600	OK		
7.	HP	CLJ 3600n	OK		
8.	HP	CLJ 3600dn	OK		
9.	HP	CLJ 3700	OK		
10.	HP	CLJ 4600	OK		
11.	HP	CLJ 5500	x		
12.	HP	CLJ 5500dn	x		
13.	HP	CLJ CP3505	OK	OK	
14.	HP	LaserJet 2605	OK		
15.	HP	LaserJet 2700	OK		
16.	HP	LaserJet 4650	OK		
17.	HP	CM1015MFP	OK		
18.	HP	CM1017MFP	OK		
19.	HP	LaserJet 1012	OK		
20.	HP	LaserJet 1015	OK		
21.	HP	LaserJet 1022	OK	OK	(Note2)
22.	HP	LaserJet 1200	OK		
23.	HP	LaserJet 1220	OK		
24.	HP	LaserJet 1300	OK		
25.	HP	LaserJet 1320	OK		
26.	HP	LaserJet 2300	OK		
27.	HP	LaserJet 2300L	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
28.	HP	LaserJet 2420	OK		
29.	HP	LaserJet 2420dn	OK		
30.	HP	LaserJet 4200L	x		
31.	HP	LaserJet 4350	OK		
32.	HP	LaserJet 5100LE	x		
33.	HP	LaserJet 5100SE	x		
34.	HP	LaserJet 5200L	OK		
35.	HP	LaserJet 3015	OK		
36.	HP	LaserJet 3020	OK	OK	
37.	HP	LaserJet 3030	OK		
38.	HP	LaserJet 3050	OK		
39.	HP	LaserJet 3050z	OK	x	
40.	HP	LaserJet 3200	OK		
41.	HP	LaserJet 3300	OK		
42.	HP	LaserJet 3330mfp	OK		
43.	HP	LaserJet 3380	OK		
44.	HP	LaserJet M1005MFP	OK	OK	
45.	HP	LaserJet P2015	OK	OK	
46.	HP	Deskjet 450	OK		
47.	HP	Deskjet 810C	OK		
48.	HP	DeskJet 845C	OK	OK	
49.	HP	Deskjet 880C	OK		
50.	HP	Deskjet 882C	OK		
51.	HP	Deskjet 895cxi	OK	OK	
52.	HP	Deskjet 920C	OK		
53.	HP	Deskjet 960	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
54.	HP	Deskjet 970cxi	OK	OK	
55.	HP	Deskjet 980	OK		
56.	HP	Deskjet 990	OK		
57.	HP	Deskjet 1120C	OK		
58.	HP	Deskjet 1125C	x		
59.	HP	Deskjet 1180C	OK		
60.	HP	Deskjet 3325	OK		
61.	HP	Deskjet 3535	OK		
62.	HP	Deskjet 3550	OK		
63.	HP	Deskjet 3650	OK		
64.	HP	Deskjet 3820	OK		
65.	HP	Deskjet 5160	OK		
66.	HP	Deskjet 5550	OK		
67.	HP	DeskJet 5652	OK		
68.	HP	DeskJet 5740	OK		
69.	HP	Deskjet 6122	OK		
70.	HP	DeskJet 6540	OK		
71.	HP	DeskJet 6840	OK		
72.	HP	DeskJet845C	OK	OK	
73.	HP	Deskjet 9300	OK		
74.	HP	Deskjet 9650	OK		
75.	HP	Deskjet D2360	OK		
76.	HP	Deskjet D4260	OK	OK	
77.	HP	Deskjet F2180	OK	OK	
78.	HP	Deskjet F380	OK	OK	
79.	HP	Business 1000	OK		
80.	HP	Business 1100d	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
81.	HP	Business 1200d	OK		
82.	HP	OfficeJet J5780	OK	OK	
83.	HP	OfficeJet Pro K5300	OK		
84.	HP	OfficeJet Pro K5400	OK		
85.	HP	OfficeJet Pro K5400dn	OK	OK	
86.	HP	OfficeJet Pro K850	OK		
87.	HP	OfficeJet Pro K850dtn	OK		
88.	HP	OfficeJet Pro L7380	OK	OK	
89.	HP	OfficeJet Pro L7580	Ok	OK	
90.	HP	OfficeJet 4110	OK		
91.	HP	OfficeJet 4255	OK	OK	
92.	HP	OfficeJet 5110	OK		
93.	HP	OfficeJet 5510	OK		
94.	HP	OfficeJet 5610	OK	OK	
95.	HP	OfficeJet 6110	OK		
96.	HP	OfficeJet 6210	OK		
97.	HP	OfficeJet 6310	OK	OK	
98.	HP	OfficeJet 7210	OK		
99.	HP	OfficeJet 7410	OK	OK	
100.	HP	OfficeJet 9100	OK		
101.	HP	OfficeJet 9110	OK		
102.	HP	OfficeJet 9120	OK		
103.	HP	OfficeJet 9130	OK		
104.	HP	OfficeJet V40	OK		
105.	HP	Photosmart 145	OK		
106.	HP	Photosmart 245	OK		
107.	HP	Photosmart 325	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
108.	HP	Photosmart 375	OK		
109.	HP	Photosmart 2575	OK	OK	
110.	HP	Photosmart 2610	OK	OK	
111.	HP	Photosmart 2710	OK		
112.	HP	Photosmart 3110	OK		
113.	HP	Photosmart 3310	OK		
114.	HP	Photosmart 7260	OK		
115.	HP	Photosmart 7550	OK		
116.	HP	Photosmart 7660	OK		
117.	HP	Photosmart 7760	OK		
118.	HP	Photosmart 7960	OK		
119.	HP	Photosmart 8450	OK		
120.	HP	Photosmart 8750	OK		
121.	HP	Photosmart A526	OK	OK	
122.	HP	Photosmart C3180	OK	OK	
123.	HP	Photosmart C4180	OK		
124.	HP	Photosmart C4280	OK	OK	
125.	HP	Photosmart C6280	OK	Ok	
126.	HP	Photosmart C7180	Ok	OK	
127.	HP	Photosmart C7280	OK	OK	
128.	HP	Photosmart D5160	OK	OK	
129.	HP	Photosmart D7160	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
130.	HP	Photosmart D7360	OK	OK	
131	HP	PSC 750	OK		
132	HP	PSC 1110	OK		
133.	HP	PSC 1210	OK	OK	
134.	HP	PSC 1315	OK	OK	
135.	HP	PSC 1350	OK		
136.	HP	PSC 1410	OK	OK	
137.	HP	PSC 1510	OK	OK	
138.	HP	PSC 1610	OK	OK	
139	HP	PSC 2110	OK		
140.	HP	PSC 2210	OK		
141.	HP	PSC 2310	OK		
142.	HP	PSC 2355	OK	OK	
143.	HP	PSC 2410	OK		
144.	HP	PSC 2510	OK		
145	HP	PSC 4110	OK		
146	Canon	iC D380	OK		
147	Canon	S200SPx	OK		
148.	Canon	C350	OK		
149	Canon	i255	OK		
150	Canon	i320	OK		
151	Canon	i355	OK		
152	Canon	i450	OK		
153	Canon	i455	OK		
154	Canon	i6100	OK		
155	Canon	i6500	OK		
156	Canon	i9100	OK		
157	Canon	i9950D	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
158	Canon	i475D	OK		
159	Canon	i560	OK		
160	Canon	i865	OK		
161	Canon	i905D	OK	OK	
162	Canon	iR 2010	OK		
163	Canon	iR 6000	x		
164	Canon	iR 8500	x		
165.	Canon	iP1000	OK		
166.	Canon	iP1880	OK	OK	
167.	Canon	iP1500	OK		
168.	Canon	iP2000	OK		
169.	Canon	iP3000	OK		
170.	Canon	iP3300	OK	OK	
171.	Canon	iP3500	OK	OK	
172	Canon	iP4000	OK		
173	Canon	iP4200	OK	OK	
174	Canon	iP4300	OK	OK	
175	Canon	iP4500	OK	OK	
176.	Canon	iP5000	OK		
177.	Canon	iP6000D	OK		
178	Canon	iP8500D	OK		
179	Canon	Pro 9000	OK		
180	Canon	iX4000	OK	OK	
181	Canon	iX5000	OK		
182.	Canon	PIXMA MP110	OK		
183.	Canon	PIXMA MP130	OK	OK	
184.	Canon	PIXMA MP150	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
185.	Canon	PIXMA MP160	OK		
186.	Canon	PIXMA MP170	OK		
187.	Canon	PIXMA MP180	OK		
188.	Canon	PIXMA MP450	OK	OK	
189.	Canon	PIXMA MP510	OK		
190.	Canon	PIXMA MP700	OK		
191.	Canon	PIXMA MP730	OK		
192.	Canon	Pro9000	OK	OK	
193.	SAMSUNG	ML-1520LP	OK		
194.	SAMSUNG	ML-1740	OK		
195.	SAMSUNG	ML-2010	OK		
196.	SAMSUNG	SCX-4100	OK		
197.	SAMSUNG	SCX-4200	OK		
198.	SAMSUNG	SCX-4521F	OK	OK	
199.	SAMSUNG	SCX-4720F	OK		
200.	SAMSUNG	SF-565P	OK	OK	
201.	Lexmark	X6170	OK	Vista 64 only	
202.	Lexmark	Z603	OK		(Note1)
203.	Lexmark	Z615	OK		(Note1)
204.	Lexmark	Z705	OK		(Note1)
205.	Lexmark	Z810	OK		(Note1)
206.	Lexmark	Z816	OK		(Note1)
207.	Lexmark	Z818	OK	Vista 32 only	(Note1)
208.	Lexmark	E230	OK		
209.	Lexmark	C510	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
210.	Epson	Aculaser C1900	OK		
211.	Epson	Aculaser C4000	OK		
212.	Epson	Aculaser C4100	OK		
213.	Epson	Aculaser C8600	OK		
214.	Epson	DLQ-3500C	OK		
215.	Epson	EPL-5900L	OK	Vista32 only	(Note2)
216.	Epson	EPL-6100	OK		
217.	Epson	EPL-6200	OK	Vista32 only	
218.	Epson	EPL-N2500	OK		
219.	Epson	EPL-N2750	x		
220.	Epson	EPL-N3000	OK		
221.	Epson	LQ-300+	x		
222.	Epson	LQ-300+II	OK	Vista32 only	
223.	Epson	LQ-680C	x		
224.	Epson	LQ-2080C	x		
225.	Epson	Stylus C43UX	OK		
226.	Epson	Stylus C45	OK	OK	
227.	Epson	Stylus C63	OK		
228.	Epson	Stylus C83	OK		
229.	Epson	Stylus C4100	OK	OK	
230.	Epson	Stylus COLOR 740	OK	OK	
231.	Epson	Stylus COLOR 880	OK		
232.	Epson	Stylus COLOR 1160	OK		
233.	Epson	Stylus CX1500	OK		
234.	Epson	Stylus CX3100	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
235.	Epson	Stylus CX3700	OK		
236.	Epson	Stylus CX3900	OK	OK	
237.	Epson	Stylus CX4700	OK	OK	
238.	Epson	Stylus CX5100	OK		
239.	Epson	Stylus CX5300	OK		
240.	Epson	Stylus CX5500	OK	OK	
241.	Epson	Stylus CX5900	OK	OK	
242.	Epson	Stylus PHOTO 830U	OK		
243.	Epson	Stylus PHOTO 935	OK		
244.	Epson	Stylus PHOTO 1390	OK	OK	
245.	Epson	Stylus PHOTO 2100	OK		
246.	Epson	Stylus PHOTO R210	OK		
247.	Epson	Stylus PHOTO R230	OK		
248.	Epson	Stylus PHOTO R310	OK	OK	
249.	Epson	Stylus PHOTO RX430	OK		
250.	Epson	Stylus PHOTO RX510	OK		
251.	Epson	Stylus PHOTO RX530	OK	OK	
252.	Epson	Stylus PHOTO RX590	OK	OK	
253.	Epson	Stylus PHOTO RX630	OK		

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.

Print Server Compatible Tested List

No.	Company	Printer Model	USB Port	Windows Vista 32/64	Note
254.	Epson	Stylus PHOTO RX650	OK	OK	
255.	Brother	HL-2070	OK		
256.	Brother	HL-5240	OK		
257.	Brother	MFC-210C	OK		
258.	Brother	MFC-215C	OK		
259.	Brother	MFC-2820	OK		
260.	Brother	MFC-3240C	OK		
261.	Brother	MFC-420CN	OK		
262.	Brother	MFC-425CN	OK		
263.	Brother	MFC-4800J	OK		
264.	Brother	MFC-7420	OK		
265.	Brother	MFC-7820N	OK		
266.	Brother	MFC-8840D	OK		
267.	Konica Minolta	Magicolor 2480MF	OK	Vista 32 only	(Note2)
268.	Konica Minolta	Magicolor 5550	OK		
269.	Konica Minolta	Magicolor 5570	OK		
270.	Dell	944	OK		
271.	Dell	Mono LaserMFP1125	OK		(Note2) No Win2000

“X” means not compatible

Note1 : For some of Lexmark printers, please close bi-directional and choose “WinPrint” processor and RAW printing protocol.

Note2 :This model needs to close bi-directional function.